

Technician:

# Pre Scan Vehicle System Report

2007 Audi Q7 4.2L FSI 4.2L FSI (BAR)

VIN WA1EV74L57D085807

Odometer

License

September 11, 2020 7:55 AM

## CODE SCAN RESULTS

Systems Analyzed: 31

### Systems w/ Codes

#### 01-Engine Management

- 01112 | EVAP System Purge Control Valve (N80) Short to Ground P0458 Lower Limit Reached
- 00258 | Mass Air Flow Sensor (G70) Signal too Low P0102 Lower Limit Reached
- 00268 | Mass Air Flow Sensor (G246) Signal too Low P010C Lower Limit Reached
- 08853 | Fuel Pressure Regulator Valve (N276) Short to Ground P2295 Lower Limit Reached
- 04764 | Fuel Pressure Regulator Valve; Bank 2 (N276) : Short to Ground P129C Lower Limit Reached
- 05173 | Secondary Air Pump Relay (J299) Short to Ground P1435 Lower Limit Reached
- 00048 | Oxygen (Lambda) Sensor B1 S1: Heating Circuit: Malfunction / Open Circuit P0030 No Signal/No Communication
- 00080 | Oxygen (Lambda) Sensor B2 S1: Heating Circuit: Malfunction / Open Circuit P0050 No Signal/No Communication
- 09217 | EVAP Leak Detection Pump Control Circuit Short to Ground P2401 Lower Limit Reached

---

#### 02-Transmission

- 01314 | Engine Control Module Read Trouble Codes

---

#### 03-Brake Electronics

- 01826 | Sensor for Steering Angle (G85) Supply Voltage Terminal 30
- 01314 | Engine Control Module Read Trouble Codes

---

#### 0E-Media Player Position

- 02095 | Component Protection: Active
-

### **19-Diagnostic Data Interface-Gateway**

01301 | Control Module for Voice Recognition (J507) No Signal/No Communication

---

### **1E-Media Player Position 2**

00532 | Supply Voltage B + Lower Limit Reached - Intermittent

---

### **37-Navigation System**

00862 | Antenna for GPS Navigation (R50/R52) Open Circuit

---

### **3C-Lane Change Assistant**

02850 | Control Module 2 for Lane Change Assistance (J770) Malfunction

---

### **42-Door Electronics Driver**

02126 | Central Door Locking (CDL) Button: Exterior Door Handle Not A Plausible Signal

---

### **46-Comfort Systems**

01134 | Alarm Horn (H12) Electrical Problem In Circuit

---

### **52-Door Electronics Passenger**

02126 | Central Door Locking (CDL) Button: Exterior Door Handle Not A Plausible Signal

---

### **56-Radio**

00856 | Radio Antenna Open Circuit

00858 | Connection Radio ZF Output to Antenna Amplifier Open Circuit

---

### **62-Door Electronics Rear Left**

02126 | Central Door Locking (CDL) Button: Exterior Door Handle Not A Plausible Signal

---

### **6C-Back Up Camera**

00778 | Steering Angle Sensor (G85) Read Trouble Codes

---

### **6D-Trunk Electronics**

00317 | Rear Lid Control Module (J605) Not A Plausible Signal - Intermittent

00447 | Function Limitation due to Over - Voltage Upper Limit Reached - Intermittent

02786 | Module 2 for Hatch / Trunk Lid (J756) Upper Limit Reached - Intermittent

02072 | ECU For Energy Management - J644 No Signal/No Communication - Intermittent

---

## 77-Telephone

01042 | Control Module Not Coded

---

### ✔ Systems w/o Codes

05-Start Auth-Kessy-Entry  
08-Airco  
09-Central Electronics  
0F-Digital Radio Tuner  
15-Airbag - SRS  
16-Steering Wheel Electronics  
17-Instrument Cluster  
36-Seat Memory Driver  
47-Audio System  
4F-Central Electronics II  
55-Level Control Xenon Lights  
61-Battery Regulation  
6F-Comfort Electronics II  
72-Door Electronics Rear Right  
76-Parking Help  
OBDII Codes (\$03)  
OBDII Permanent Codes (\$0A)

## READINESS MONITORS

### ✔ Complete

Misfire  
Fuel System  
Comprehensive Component

---

### ● Not Complete

Catalyst  
Evaporative System  
Secondary Air System  
Oxygen Sensor  
Oxygen Sensor Heater

