

Pre Scan

Vehicle System Report

VEHICLE INFORMATION

MAKE	GMC
YEAR	2015
MODEL	Sierra (4WD)
ENGINE	5.3L V8 (L83)
SYSTEM	CodeScan
VIN	3GTU2UEC9FG362466
ODOMETER	66303 mi

CODE SCAN RESULTS

Systems Analyzed: 19

- ✔ Engine: 0
- ✔ Transmission: 0
- ✔ Antilock Brakes: 0
- ✔ Airbag: 0
- ✔ Body Control Module: 0
- ✔ Human Machine Interface: 0
- ✔ HVAC: 0
- ✔ HVAC Controls: 0
- ✔ Instrument Panel Cluster: 0
- ✔ Passenger Presence System: 0
- ✔ Power Steering Control Module: 0
- ⚠ Radio: 2
- ✔ Radio Controls: 0
- ✔ Steering Wheel Angle Sensor: 0
- ✔ Telematics Communication Interface: 0
- ✔ Tire Pressure Monitor: 0
- ✔ Transfer Case: 0
- ✔ OBDII Codes (\$03): 0
- ✔ OBDII Permanent Codes (\$0A): 0

Radio

B1325 | Control Module Power Circuit Voltage Below Threshold (Symptom 03) - Test Failed Since DTC Clear, History DTC.

U0164 | Lost Communication with HVAC Control Module (Symptom 00) - Test Failed Since DTC Clear, History DTC.

READINESS MONITORS

Tests Complete

- ✔ Misfire
- ✔ Fuel System
- ✔ Comprehensive Component
- ✔ EGR/VVT
- ✔ Catalyst
- ✔ Evaporative System
- ✔ Oxygen Sensor
- ✔ Oxygen Sensor Heater

