

Technician:

# Pre Scan Vehicle System Report

**2012 Volkswagen Polo 1.2L MPI (CGPB)**

VIN                      WWWZZZ6RZCY019910

Odometer              200,590

License

24 November, 2021 8:13 AM

## CODE SCAN RESULTS

Systems Analyzed: 11

### Systems w/ Codes

#### 01-Engine Management

P030100 Cylinder 1 Misfire Detected

P030300 Cylinder 3: Misfire Detected

P017100 Fuel Trim,Bank 1 System too Lean

---

#### 09-Central Electronics

00967 Left Turn Signals Open Circuit/Short With Power - Intermittent

---

#### OBDII Codes (\$03)

P0171 System Too Lean Bank 1

### Systems w/o Codes

03-Brake Electronics

08-Airco

15-Airbag - SRS

17-Instrument Cluster

19-Diagnostic Data Interface-Gateway

25-Immobilizer

2E-Media Player Position 3

44-Steering Assist (separated)

56-Radio

OBDII Permanent Codes (\$0A)

## READINESS MONITORS

✔ Complete

Misfire  
Fuel System  
Comprehensive Component  
Catalyst  
Evaporative System  
Oxygen Sensor  
Oxygen Sensor Heater

---

● Not Complete

